


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-241	Smoke	8/24/2009	ADS/TM	S19QQ_005MH	Dry	Yes	806.74



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-241	Smoke	8/24/2009	ADS/TM	S19QQ_005MH	Dry	Yes	806.74

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19QQ_022G1	S19QQ_022DE	S19QQ_008MH	109.036	8
S19QQ_008G1	S19QQ_008MH	S19QQ_005MH	179.675	8
S19QQ_020G1	S19QQ_020DE	S19QQ_010MH	31.1386	8
S19QQ_006G1	S19QQ_006MH	S19QQ_008MH	99.8219	8
S19QQ_005G1	S19QQ_005MH	S19QQ_010MH	236.677	8
S19QQ_010G1	S19QQ_010MH	S19QQ_001MH	140.622	8
S19QQ_003G1	S19QQ_003MH	S19QQ_006MH	9.77085	8

### Observations & Photos

**Obs\_ID** S1028-241-OB01

**Address** 2205 Liberty Heights Ave


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19QQ\_008MH

**Comments** Smoke from cleanout in back yard. 2205 Liberty Heights Ave.



**Picture** \S1028-241-OB01-P01.jpg

**Comments** Back of house, 2205 Liberty Heights Ave.

**Obs\_ID** S1028-241-OB02

**Address** 3414 Woodbrook Ave


**Status** Private

**Source** Service Lateral

**Location** Paved concrete

**Nearest MH** S19QQ\_005MH

**Comments** Smoke from service lateral under paved concrete behind house. 3414 Woodbrook Ave.



**Picture** \S1028-241-OB02-P01.jpg

**Comments** Back of house, 3414 Woodbrook Ave.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-241	Smoke	8/24/2009	ADS/TM	S19QQ_005MH	Dry	Yes	806.74

**Obs\_ID** S1028-241-OB03

**Address** 2521 Reisterstown Rd


**Status** Private

**Source** Service Lateral

**Location** Paved concrete

**Nearest MH** S19QQ\_010MH

**Comments** Smoke from service lateral under paved concrete stairs behind house. 2521 Reisterstown Rd.



**Picture** \S1028-241-OB03-P01.jpg

**Comments** Back of house, 2521 Reisterstown Rd.

**Obs\_ID** S1028-241-OB05

**Address** 1706 Gwynns Falls Pkwy

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19QQ\_010MH

**Comments** Smoke from cleanout in back yard. 1706 Gwynns Falls Pkwy.



**Picture** \S1028-241-OB05-P01.jpg

**Comments** Back of house, 1706 Gwynns Falls Pkwy.

**Obs\_ID** S1028-241-OB04

**Address** 3412 Woodbrook Ave


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19QQ\_005MH

**Comments** Smoke from cleanout in back yard. 3412 Woodbrook Ave.



**Picture** \S1028-241-OB04-P01.jpg

**Comments** Back of house, 3412 Woodbrook Ave.